





In order to improve performance of Kalix POU watercoolers, OASIS are introducing a new range of solenoid valves for use in all 230V products – cook and cold, hot and cold, and carbonated models. Extended testing of the new valves show that they are more resistant to fluctuating water pressures, prevent dripping and can withstand higher pressures without leaking.

These valves are a direct replacement for the original equipment – please note that the quick-fit connection that screws to the valve must also be changed.

Service kits have been created to supply all necessary parts to replace a faulty solenoid valve assembly.

Important Note:		
	Original	Revised
OASIS Part Number	034613-001(230v)	037592-001(230v)
Appearance		
OASIS Part Number	034613-003(230v)	
Appearance		

OASIS Part Number	034613-004 (24VDC)	037592-003 (24VDC)
Appearance		
OASIS Part Number	034377-002	037591-001
Appearance		

Service Kit



Kit Number	Description	Kit Contents		
		Part Number	Description	Quantity
037756p001	SERVICE KIT, 230V	037591-001	1/4" QUICK FIT CONNECTION	x 2
		037592-001	SOLENOID VALVE, 230V	x 1
037756p002	SERVICE KIT, 24V	037591-001	1/4" QUICK FIT CONNECTION	x 2
		037592-003	SOLENOID VALVE, 230V	x 1



Note:
This terminal is not used in Kalix system.